

P 171549Z

FM NPIC WASHDC

TO RUCSC/SAC OFFUTT AFB OMAHA NEB  
 RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA  
 RUCVAA/2D RTS BARKSDALE AFB LA  
 RUEKDA/DIA WASHDC  
 RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD  
 RUEPIA/CIA WASHDC  
 RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF  
 RUWGAA/2 AF BARKSDALE AFB LA  
 BT

S E C R E T CITE NPIC 7504.

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

1. CAMERA B 125 WAS USED IN MISSION 6098 FLOWN ON 5 JUNE  
 1966 PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

## 2. ORIGINAL NEGATIVE:

A. EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: MINOR EDGE STATIC IS PRESENT ON BOTH  
 FILM EDGES THROUGHOUT THE MISSION. THE LEADING FIDUCIAL  
 ALONG THE OUTBOARD EDGE IS PARTIALLY OBSCURED DUE TO  
 FOREIGN MATTER BUILD-UP. THE TITLING IS BLOCKED ON ALTERNATE  
 FRAMES 10 THROUGH 80 AND 1504 THROUGH 1592. THE VERTICAL  
 DOT INDICATOR IMAGE IS OVEREXPOSED. A MANUFACTURER'S  
 SPLICE IS LOCATED IN FRAME 238 WITH ASSOCIATED INDENTIONS  
 AND STATIC TRACES ON FRAMES 236/237 AND 239.

C. 9L SIDE: MINOR EDGE STATIC IS PRESENT ON THE  
 OUTBOARD EDGE OF THE FILM ON FRAMES 1 THROUGH 300. AN  
 EMULSION SCRATCH AND A MANUFACTURER'S SPLICE IS IN FRAME  
 1491.

D. BOTH SIDES: SEVERAL FRAMES ARE SMEARED DUE TO  
 VEHICLE MANEUVERS. (EXAMPLES: FRAMES 417, 1013 AND 1209)  
 THE FRAMES ARE TITLED CONSECUTIVELY FROM 000 THROUGH 1655.

20 JUN 1966		
DISTRIBUTION		
Cy No.	Office	Action
2	OS	
	ADMMI	
	SEC BR	
	P & DS	
	CSD	
	IPD	
	PD	
	PSD	
	PSD-ICB	
	TID	
	IAD	
	PAG	
	DIAXX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

345  
 Advance copy  
 Sanitized



--2--

THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.

3. POSITIVE:

- A. PI SUITABILITY IS GOOD.
- B. PRINTING AND PROCESSING WERE GOOD.
- C. CLOUDS DEGRADE OR OBSCURE APPROXIMATELY 45 PERCENT OF THE MISSION.

GP-1

S E C R E T

-END OF MESSAGE-